

No.TM-PS5-0133E-01

Issued Date: Jun, 3, 2021

Sony Interactive Entertainment Inc.  
CS Dept.




Tel:+81(50)-3807-9360

Fax:+81(50)-3807-9595



SIE Inc.

## *Technical Memo*

Approved by	Checked by	Drawn by
		

Subject. Note for the MCB block manufactured by VSH1.02.

Description. PI-2 test is failed by using the MCB block manufactured by VSH1.02  
after JIG SW had been released for VSH3.00.

When exchanging MCB block, you must upgrade the system software to version 3.00  
by using Update Software (DG-PS5-0121E-xx) before running the PI-2 test.  
This process is not necessary if you use the MCB block manufactured by VSH2.00 or later.  
The MCB blocks ordered from 2020 Nov, are manufactured by VSH2.00 or later.

This process is not necessary after JIG SW will be switched for VSH4.00. (about 2021 Sep.)