



SIE Inc.

Technical Memo

Approved by	Checked by	Drawn by
		

Subject. About the combination of MCB repair parts

Description. MCB BLOCK has combination by a vendor of GDDR6.
When repairing MCB BLOCK, use the following combination.

Parts		GDDR6 Vender	Samsung	Micron	Hynix
With Drive	MCB	EDM-010 MOUNT(E)(S) A-5021-710-A	EDM-010 MOUNT(E)(M) A-5024-586-A	EDM-010 MOUNT(E)(H) A-5024-590-A	
	MCB ID (leading 5 digits of board ID)	40001	40003	40005	
		40002	40004	40006	
		179SC	AA001		
			AA002		
			AA003		
			AA004		
			AA005		
			AA006		
Without Drive	MCB	EDM-010 MOUNT(D)(S) A-5023-189-A	EDM-010 MOUNT(D)(M) A-5024-595-A	EDM-010 MOUNT(D)(H) A-5024-599-A	
	MCB ID (leading 5 digits of board ID)	40007	40009	40011	
		40008	40010	40012	
		179ZC			
Heatsink G6 A 5-022-928-01		✓		✓	
Heatsink G6 B 5-022-929-01		✓		✓	
Thermal Grease (SMX-8332) 7-640-026-18		✓		✓	
SHEET (3(43.5X10.5)),RADIATION 5-022-930-02		✓		✓	
SHEET (3(88X12)), RADIATION 5-022-930-12		✓		✓	
SHEET (3.5(60X20)), RADIATION 5-022-931-02		✓		✓	