

No.TM-PS5-0053E-02

Issued Date: Jul. 20. 2021

Sony Interactive Entertainment Inc.
CS Dept.

Tel:+81(50)-3807-9360

Fax:+81(50)-3807-9595



SIE Inc.

Technical Memo

Approved by	Checked by	Drawn by

Subject. Product code for MCB Repair

Description. Please use the following product code for the console inspection of MCB repair Commit process.

Chassis	RHQ	Model	Product code	note
A	SIEJA Japan	with drive	27418892	J1
		without drive	27418882	J1
	SIEA	with drive	27418871	UCS
		without drive	27418880	UCS
	SIEE	with drive	27418872	EU8
		without drive	27418877	EU8
	SIEK	with drive	27418888	E32
		without drive	27418881	E32
B	SIEJA Japan	with drive	27418984	J1
		without drive	27418995	J1
	SIEA	with drive	27418950	UCS
		without drive	27418954	UCS
	SIEE	with drive	27418948	EU8
		without drive	27418952	EU8
	SIEK	with drive	27418982	E32
		without drive	27418991	E32

Target model CFI-1000/1100 series

CONFIDENTIAL AND PRIVILEGED